

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DF532
East
1/2-1
0.821 mi.
4337 ft.

CONSTRUCTION SITE
2929 BRIGHTON 5TH ST
BROOKLYN, NY

NY Spills **S111318841**
N/A

Site 2 of 2 in cluster DF

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: CONSTRUCTION SITE
Address: 2929 BRIGHTON 5TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1110000 / 2011-11-25
Facility ID: 1110000
Facility Type: ER
DER Facility ID: 412273
Site ID: 457797
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2011-11-09
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-11-09
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-11-09
Spill Record Last Update: 2011-11-25
Spiller Name: ALEX NAD
Spiller Company: NADKOS INC
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JOHN WILSON
DEC Memo: "leaking vehicle belongs to DEP subcontractor. Cleanup is completed under DEP supervision."

Remarks: "cleanup in progress as active leak"

All Materials:

Site ID: 457797
Operable Unit ID: 1207916
Operable Unit: 01
Material ID: 2205227
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: Not reported
Oxygenate: Not reported